I & Final Bill

AEE/SWD/Y.Anc/587 04/475

M. A. R. 57 (Rule 116)
Measurement Book

No. B 2014-15/533

Serial No. .....

Name of work Remodeling of SWD and its allied works in Critical low lying area (Flood prone area) at Bhadrappa layout, Nagathathalli, To Sangaya nagara in yelahanka zone

Name of Contractor of nature of Agency M/s Deccan Engineers and Constructions

Date of commencement of work 23/07/2014

Date	Full description, etc, of work	Dimensions				Contents	Reference to last Measurement
		Number	Length	Breadth	Depth		
1	2	3	4	5	6	7	8
	Estimated Cost :	156.57 Lakhs					
	Work code :	008-12-000060					
	Administrative Sanction No:	CE/SWD/Admn/50/2012-13, Dated: 10/4/2012					
	Technical Sanction No:	CE/SWD/Tech-Sanction/50/2012-13, Dated: 10/4/2012					
	Work Order No. :	BBMP/EE/Y2/SWD/WO/06/12-13, Dated: 15/03/2013					
	Agreement No. & Date:	BBMP/EE/SWD/Y2/06/12-13, Dated: 18/03/2013					
	Cost of Tender :	Rs. 1,77,91,894-00					
	Tender percentage :	10.25% Above 2012-13 SR					
	Period of Completion of work:	6 months from the date of issue of work order					17-09-2013
	Site Handed over date :	21/7/2014. After shifting of HT over Supply lines					
	~~Actual date of completion~~	31/10/2014.					

Scanned by CamScanner

M. A. R. 57 (Rule 116)
Measurement Book

No. B 85551

Serial No. .....

Name of work ..... From ..... To .....

Name of Contractor of nature of Agency.....

Date of commencement of work.....

Date	Full description, etc, of work	Number	Dimensions Length	Breadth	Depth	Contents	Reference to last Measurement
1	2	3	4	5	6	7	8
29	11 KV Horizontal X Qty as per MS Excel sheet page no: 26 of 26		10 x 0.90 Set @ Rs 77.18/set = Rs.				694-00
						Total	1,77,90,251=00
							1,77,90,200

Certificate

1) Certified that the work executed by the Contractor is satisfactory.
2) Certified that the Contractor has removed debris from the work side.
3) Certified that the Contractor has completly used RMC only

AE/SWD/42
28/11/14

28/11/14

Assistant Executive Engineer
Storm Water Drain Sub Division,
Yelahanka zone,
Bruhat Bengaluru Mahanagara Palike

Scanned by CamScanner

MEASUREMENT BOOK

Full description, etc, of work 2	Dimensions Number 3	Length 4	Breadth 5	Depth 6	Contents 7	Reference to last Measurement 8
Location Map  						

AEE(CWD) Y2
28/11/2014

Scanned by CamScanner

Ist & final bill

BR-NO. 205 / 29-11-2014.

M. A. R. 57 (Rule 116)
Measurement Book

No. B 85552

Serial No. .....

Name of work ..... From ..... To .....

Name of Contractor of nature of Agency .....

Date of commencement of work .....

Date	Full description, etc, of work	Number	Dimensions: Length	Dimensions: Breadth	Depth	Contents	Reference to last Measurement
1	2	3	4	5	6	7	8
	Present Bill 1,77,90,200					1,77,90,200	
	Dismantling Rubble stone masonry I I 2% 3,55,810=00						
	Vat 4% 7,11,610=00						
	60980=00						
	Royalty 37,580=00						
	CBFO.1% 17,790=00						
	Ucel 1% 1,77,910=00						
	Deduction 13,00,700				1,64,57,050		
	13,33,150=00				1,64,89,500		
	nil 1,64,89,500				13,00,700	13,33,150=00	
	1,64,57,050=00						

Scanned by CamScanner